# DO NOT USE THIS DOCUMENT FOR REPORTING PURPOSES. THIS DOCUMENT IS FOR GUIDANCE AND INSTRUCTION ONLY

# **Year 5 Annual Report**

## New Hampshire Small MS4 General Permit New Permittees

Reporting Period: July 1, 2022-June 30, 2023

Section 1.10.3 - Timelines for New Permittees

\*\*Please DO NOT attach any documents to this form. Instead, attach all requested documents to an email when submitting the form. Also ensure any websites included on this form are to publicly accessible sites\*\*

Unless otherwise noted, all fields are required to be filled out. If a field is left blank, it will be assumed the requirement or task has not been completed. Please ONLY report on activities between July 1, 2022 and June 30, 2023 unless otherwise requested.

### **Part I: Contact Information**

Name of Municipality or Organization:	
EPA NPDES Permit Number.	
Primary MS4 Program Manager Contact Info	ormation
Name:	Title:
Street Address Line 1:	
Street Address Line 2:	
City: State:	NH Zip Code:
Email:	Phone Number:
Stormwater Management Program (SWMP)	
SWMP Location (publicly available web addres	s):
Date SWMP was Last Updated:	
If the SWMP is not available on the web please	provide the physical address:

### Part II: Self-Assessment

First, in the box below, select the impairment(s) and/or TMDL(s) that are applicable to your MS4. Make sure you are referring to the most recent EPA approved Section 303(d) Impaired Waters List which can be found here: https://www.epa.gov/tmdl/region-1-impaired-waters-and-303d-lists-state

<u>Impairmen</u>	t(s)			
ттран теп	Bacteria/Pathogens □	⊠ Chloride	⊠ Nitrogen =	
	⊠ Solids/ Oil/ Grease (Hydro			
TMDL(s)				
	⊠ Bacteria and Pathogen		∠ Lake and Pond	l Phosphorus
			Clea	ar Impairments and TMDLs
Year 5 Requ	<u>uirements</u>		<del>_</del>	
☐ Com	pleted Phase I of system mapp	oing 📃		
	tified each outfall and intercon		g from MS4, classified	into the relevant category,
and r	priority ranked each catchment			
	O The priority ranking of			
	C The priority ranking of	outralis/interconnec	ctions can be found at	the following website:
you have co	off all requirements below tha	<b>ent fully. <mark>F</mark></b> ou ha	ve not completed a req	
unchecked	Additional information will be	requested in later	sections.	
Annual Req	uirements			
Prov	ided an opportunity for public State Public Notice requireme		riew and implementation	on of SWMP and complied
☐ Kept	records relating to the permit	available for 5 year	rs and made available	to the public
	SSO inventory has been update emented	ed, including the sta	atus of mitigation and	corrective measures 📁
	O This is not applicable be	ecause we do not h	ave sanitary sewer	
	○ This is not applicable be	ecause we did not f	ind any new SSOs	
	O The updated SSO inven	tory is attached to	the email submission	
	<ul> <li>The updated SSO inven</li> </ul>	tory can be found a	at the following public	ly available website:

☐ Provided training to employees involved in IDDE program within the reporting period 📃
Properly stored and disposed of catch basin cleanings and street sweepings so they did not discharge to receiving waters
☐ All curbed roadways were swept at least once within the reporting period ☐
Enclosed all road salt storage piles or facilities and implemented winter road maintenance procedures to minimize the use of road salt
Implemented SWPPPs for all permittee owned or operated maintenance garages, public works yards, transfer stations, and other waste handling facilities
☐ Updated inventory of all permittee owned facilities as necessary 📁
O&M programs for all permittee owned facilities have been completed and updated as necessary
Implemented all maintenance procedures for permittee owned facilities in accordance with O&M programs
$\square$ Implemented program for MS4 infrastructure maintenance to reduce the discharge of pollutants $\overline{m arphi}$
☐ Inspected all permittee owned treatment structures (excluding catch basins) 🗾
Bacteria/ Pathogens (Combination of Impaired Waters Requirements and TMDL Requirements as Applicable)
Annual Requirements
Public Education and Outreach*  Annual message was distributed encouraging the proper management of pet waste, including noting any existing ordinances where appropriate
Permittee or its agents disseminated educational material to dog owners at the time of issuance or renewal of dog license, or other appropriate time
Provided information to owners of septic systems about proper maintenance in any catchment that discharges to a water body impaired for bacteria
* Public education messages can be combined with other public education requirements as applicable (see Appendix $H$ and $F$ for more information)
Optional you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:

Chloride Impairment
☐ Completed the Salt Reduction Plan
Reported amount of salt applied to all municipally owned and maintained surfaces using the UNH Technology Transfer Center online tool
Optional. If you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:
Nitrogen Impairment
Annual Requirements
Public Education and Outreach*  Distributed an annual message in the spring (April/May) that encourages the proper use and disposal of grass clippings and encourages the proper use of slow-release fertilizers  Distributed an annual message in the summer (June/July) encouraging the proper management of pet waste, including noting any existing ordinances where appropriate  Distributed an annual message in the fall (August/September/October) encouraging the proper disposal of leaf litter  * Public education messages can be combined with other public education requirements as applicable (see Appendix H and F for more information)
Good Housekeeping and Pollution Prevention for Permittee Owned Operations
Increased street sweeping frequency of all municipal owned streets and parking lots subject to Permit part 2.3.7.a.iii.(c) to a minimum of two times per year (spring and fall)
Potential Structural BMPs
Any structural BMPs listed in Table 3 of Attachment 1 to Appendix F already existing or installed in the regulated area by the permittee or its agents was tracked and the nitrogen removal by the BMP was estimated consistent with Attachment 1 to Appendix F. The BMP type, total area treated by the BMP, the design storage volume of the BMP and the estimated nitrogen removed in mass per year by the BMP were documented.
○ No BMPs were installed
<ul> <li>The BMP information is attached to the email submission</li> <li>The BMP information can be found at the following publicly available website:</li> </ul>
The Bivit information can be found at the following publicity available website.
Optional: To you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:

Phosphorus Impairment
Annual Requirements
Public Education and Outreach*
Distributed an annual message in the spring (April/May) encouraging the proper use and disposal of grass clippings and encouraging the proper use of slow-release and phosphorus-free fertilizers
Distributed an annual message in the summer (June/July) encouraging the proper management of pet waste, including noting any existing ordinances where appropriate
Distributed an annual message in the fall (August/September/October) encouraging the proper disposal of leaf litter
* Public education messages can be combined with other public education requirements as applicable (see Appendix H and $F$ for more information)
Good Housekeeping and Pollution Prevention for Permittee Owned Operations
Increased street sweeping frequency of all municipal owned streets and parking lots subject to Permit part 2.3.7.a.iii.(c) to a minimum of two times per year (spring and fall)
Potential structural BMPs
Any structural BMPs already existing or installed in the regulated area by the permittee or its agents
was tracked and the phosphorus removal by the BMP was estimated consistent with Attachment 3 to Appendix F. The BMP type, total area treated by the BMP, the design storage volume of the BMP and the estimated phosphorus removed in mass per year by the BMP were documented.
○ No BMPs were installed
<ul> <li>The BMP information is attached to the email submission</li> </ul>
○ The BMP information can be found at the following website:
Total estimated phosphorus removed in <b>lbs/year</b> from the installed BMPs: 0
Optional: You would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:
Solids, Oil and Grease (Hydrocarbons), or Metals Impairment(s)
Annual Requirements
Good Housekeeping and Pollution Prevention for Permittee Owned Operations
Increased street sweeping frequency of all municipal owned streets and parking lots to a schedule that 💆

Good Housekeeping and Pollution Prevention for Permittee Owned Operations
Increased street sweeping frequency of all municipal owned streets and parking lots to a schedule that targets areas with potential for high pollutant loads
The street sweeping schedule is attached to the email submission
O The street sweeping schedule can be found at the following publicly available website:
The street sweeping schedule can be found at the following publicly available website.

Optional. You would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:
Chloride TMDL Annual Requirements
Implemented Chloride Reduction Plan or Alternative Chloride Reduction Plan
Reported amount of salt applied to all municipally owned and maintained surfaces using the UNH  Technology Transfer Center online tool
Optional in you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:
Lake and Pond Phosphorus TMDL
Completed the written Phase 1 Lake Phosphorus Control Plan (LPCP), including: (select the items in the Phase 1 LPCP that have been completed)
☐ Planned nonstructural controls =
☐ O&M program for structural controls
☐ Implementation schedule
Cost of implementation The Phase 1 LPCP: (select one of the following options)
is attached to the email submission
C can be found at the following publicly available website:
Baseline phosphorus export reduction required from LPCP Area vs/ 0 year):
Optional. If you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:
Optional. The the box below to provide any additional information you would like to share as part of your self-assessment:

Page /

# Part III: Receiving Waters/Impaired Waters/TMDL

Have you made any changes to your lists of receiving waters, outfalls, or impairments since the NOI was
submitted?
○ Yes
O No
If yes, describe below, including any relevant impairments or TMDLs:

## **Part IV: Minimum Control Measures**

Please fill out all of the metrics below. If applicable, include in the description who completed the task if completed by a third party.

MCM1: Public Education
Number of educational messages completed during this reporting period:
Below, report on the educational messages completed <b>during this reporting period.</b> For the measurable goal(s) please describe the method/measures used to assess the overall effectiveness of the educational program.
BMP:[Message name here]
Message Description and Distribution Method:
Targeted Audience:
Responsible Department/Parties:
Measurable Goal(s):
Message Date(s):
Message Completed for: Appendix F Requirements  Appendix H Requirements
Was this message different than what was proposed in your NOI? Yes O No O
If yes, describe why the change was made:
Add an Educational Message
MCM2: Public Participation
Describe the opportunity provided for public involvement in the development of the Stormwater Management
Program (SWMP) during this reporting period:

	ortunity different than what was proposed in your NOI? Yes O No O other public involvement or participation opportunities conducted <b>during this reporting</b>
	MCM3: Illicit Discharge Detection and Elimination (IDDE)
Sanitary Sew	ver Overflows (SSOs)
•	box below if the statement is true.
	This SSO section is NOT applicable because we DO NOT have sanitary sewer
Below, report	t on the number of SSOs identified in the MS4 system and removed during this reporting period.
2010 III, 1 <b>0</b> p 01 1	Number of SSOs identified: 0
	Number of SSOs removed: 0
MS4 System	Mapping =
	all that apply.
The following	g elements of the Phase I map have been completed:
L	Outfalls and receiving waters
L	Open channel conveyances
L	Interconnections =
L	Municipally-owned stormwater treatment structures
L	Waterbodies identified by name and indication of all use impairments
	Initial catchment delineations
Optional.	escribe any additional progress you made on your map during this reporting period or provide
	atus information regarding your map:
additional Sta	
additional sta	

If conducted, please submit any outfall monitoring results from this reporting period. Outfall monitoring
results should include the date, outfall/interconnection identifier, location, weather conditions at time of sampling, precipitation in previous 48 hours, field screening parameter results, and results from all analyses.
Please also include the updated inventory and ranking of outfalls/interconnections based on monitoring results
O No outfalls were inspected
The outfall screening data is attached to the email submission
The outfall screening data can be found at the following publicly available website:
Below, report on the number of outfalls/interconnections screened during this reporting period.
Number of outfalls screened: 0
Below, report on the percent of total outfalls/interconnections screened to date.
Percent of outfalls screened: 0
Optional: Provide additional information regarding your outfall/interconnection screening:
Catchment Investigations  This requirement is due in Year 10 to 13.  If conducted, please submit all data collected during this reporting period as part of the dry and wet weather investigations. Also include the presence or absence of System Vulnerability Factors for each catchment.  O No catchment investigations were conducted  O The catchment investigation data is attached to the email submission  O The catchment investigation data can be found at the following publicly available website:
Below, report on the number of catchment investigations completed during this reporting period.
Number of catchment investigations completed this reporting period: 0
Below, report on the percent of catchments investigated to date.
Percent of total catchments investigated: 0
Optional: de any additional information for clarity regarding the catchment investigations below:
IDDE D
IDDE Progress =

If illicit discharges were found, please submit a document describing work conducted over this reporting period, and cumulative to date, including location source; description of the discharge; method of discovery; date of discovery; and date of elimination, mitigation, or enforcement OR planned corrective measures and schedule of removal.

0	No illicit discharges were found		
0	The illicit discharge removal report is a	attached to the	e email submission
0	The illicit discharge removal report can be found at the following publicly available website:		
	on the number of illicit discharges ident <b>ng this reporting period.</b>	tified and rem	oved, along with the volume of sewage
	Number of illicit discharges identified:	0	
	Number of illicit discharges removed:	0	
	Estimated volume of sewage removed:	0	gallons/day
-	·	•	l removed to date. At a minimum, report on ective date of the permit (July 1, 2018).
	Total number of illicit discharges ident	tified: 0	
	Total number of illicit discharges remo	oved: 0	
	vide any additional information for clari removed below:	try regarding r	mere discharges identified, removed, or
Employee Tra	aining  requency and type of employee training	conducted du	ring this reporting period:
Below, report (			er Runoff Control  denforcement actions completed during
	Number of site plan reviews completed	d: <mark>0</mark>	
	Number of inspections completed: 0		
	Number of enforcement actions taken:	0	

Optional. Enter any additional information relevant to construction site plan reviews, inspections, and
enforcement actions:
MCM5. Doct Construction Stammaraton Management in New Development and
MCM5: Post-Construction Stormwater Management in New Development and
Redevelopment
Ordinance or Regulatory Mechanism
Date ordinance was completed (due in year 3):
Website of ordinance or regulatory
mechanism:
As-built Drawings 📁
Below, report on the number of as-built drawings received during this reporting period.
Number of as-built drawings received: 0
rumber of as-built drawings received.
Optional. Later any additional information relevant to the submission of as-built drawings:
Opnonal.—Liter any additional information relevant to the submission of as-built drawings:
Street Design and Parking Lots Report This section is optional and is due in Year 6.
Describe the status of the street design and parking lots assessment including any planned or completed
changes to local regulations and guidelines:
Green Infrastructure Report This section is optional and is due in Year 6.

MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  O  Number of catch basins cleaned:	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Below, report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Describe the status of the green infrastructure report including the findings and progressivactice allowable:	ss towards making the
MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Below, report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with a mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material temoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine		
Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted wish BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Relow, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total volume or featch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Catch Basin Cleaning  Catch Basin Cleaning  Catch basins inspected and cleaned, along with the total volume of material temoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine		
Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with 3MPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Catch Basin Cleaning  Catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Total number of catch basins in the MS4 system.	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Relow, report on the number of catch basins inspected and cleaned, along with the total volume of material temoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins in the MS4 system.		
Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with a mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine	Describe the status of the inventory of permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas and report on any properties that have been modified or retrofitted:  MCM6: Good Housekeeping  Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material temoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Total number of catch basins sump is more than 50% full during two consecutive routine		
MCM6: Good Housekeeping  Catch Basin Cleaning  Melow, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins cleaned:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	MCM6: Good Housekeeping  Catch Basin Cleaning  Melow, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins inspected:  Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Relow, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	etrofit Properties Inventory This section is optional and is due in Year 6.	
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	• • • • • • • • • • • • • • • • • • • •	
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material emoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Catch Basin Cleaning  Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Catch Basin Cleaning Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	MCMC. Class I II and I am in a	
Below, report on the number of catch basins inspected and cleaned, along with the total volume of material memoved from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins during this reporting period.  Number of catch basins inspected:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	MCMo: Good Housekeeping	
Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Number of catch basins inspected:  Number of catch basins cleaned:  Number of catch basins cleaned:  Total volume or mass of material removed from all catch basins:  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins:  Total number of catch basins:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Number of catch basins inspected: 0  Number of catch basins cleaned: 0  Total volume or mass of material removed from all catch basins: 0  Selow, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Number of catch basins inspected:  Number of catch basins cleaned: 0  Total volume or mass of material removed from all catch basins: 0  [Select Units]  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		ıl volume of material
Number of catch basins cleaned: 0  Total volume or mass of material removed from all catch basins: 0  [Select Unit Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Number of catch basins cleaned: 0  Total volume or mass of material removed from all catch basins: 0  [Select Units]  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Total volume or mass of material removed from all catch basins: 0 [Select Unit Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Total volume or mass of material removed from all catch basins: 0 [Select Units]  Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Below, report on the total number of catch basins in the MS4 system.  Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Number of catch basins cleaned: 0	
Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Total volume or mass of material removed from all catch basins: 0	[Select Units]
Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Total number of catch basins: 0  If applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	alow report on the total number of eateh hasing in the MSA system	
f applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	f applicable:  Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine		
Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine	Total number of catch basins. U	
		`applicable:	
inspections/cleaning events:	inspections/cleaning events:		secutive routine
		aspections/cleaning events:	

Report on the number of miles swept during th	his reporting period below.
Number of miles cleaned:	
Report either the volume or weight of street sv	weeping materials collected during this reporting period below.
O Volume of material removed:	[Select Units]
O Weight of material removed:	[Select Units]
Stormwater Pollution Prevention Plan (SW Below, report on the number of site inspection reporting period.  Number of site inspections con	s for facilities that require a SWPPP completed during this
Describe any corrective actions taken at a faci	
Describe any corrective actions taken at a fact	mty with a Swfff.
Monitoring or Study Results  Results from any other stormwater or receiving	litional Information  g water quality monitoring or studies conducted during the ve, where the data is being used to inform permit compliance or
O Not applicable	
-	ports or studies are attached to the email submission ports or studies can be found at the following website(s):
<u> </u>	on your behalf or if monitoring or studies conducted by other on of the type of information gathered or received shall be
Additional Information = =	

If any of the above year 5 requirements could not be completed due to the impacts of COVID-19, please	
identify the requirement that could not be completed, any actions taken to attempt to complete the	
requirement, and reason the requirement could not be completed below:	

*Optional:* Enter any additional information relevant to your stormwater management program implementation during the reporting period. Include any BMP modifications made by the MS4 if not already discussed above.

#### **Activities Planned for Next Reporting Period**

Please confirm that your SWMP has been, or will be, updated to comply with all applicable permit requirements including but not limited to the year 6 requirements summarized below. (Note: impaired waters and TMDL requirements are not listed below)

Yes, I agree

- Develop a report assessing current street design and parking lot guidelines and other local requirements within the municipality that affect the creation of impervious cover
- Develop a report assessing existing local regulations to determine the feasibility of making green infrastructure practices allowable when appropriate site conditions exist
- Identify a minimum of 5 permittee-owned properties that could potentially be modified or retrofitted with BMPs to reduce impervious areas

#### **Annual Requirements**

- Annual report submitted and available to the public
- Annual opportunity for public participation in review and implementation of SWMP
- Keep records relating to the permit available for 5 years and make available to the public
- Properly store and dispose of catch basin cleanings and street sweepings so they do not discharge to receiving waters
- Annual training to employees involved in IDDE program
- Update inventory of all known locations where SSOs have discharged to the MS4
- Continue public education and outreach program
- Update outfall and interconnection inventory and priority ranking and include data collected in connection with the dry weather screening and other relevant inspections conducted
- Implement IDDE program
- Review site plans of construction sites as part of the construction stormwater runoff control program
- Conduct site inspection of construction sites as necessary
- Inspect and maintain stormwater treatment structures
- Log catch basins cleaned or inspected
- Sweep all curbed streets at least annually
- Continue investigations of catchments associated with Problem Outfalls
- Implemented SWPPPs for all permittee owned or operated maintenance garages, public works yards, transfer stations, and other waste handling facilities
- Review inventory of all permittee owned facilities in the categories of parks and open space, buildings and facilities, and vehicles and equipment; update if necessary
- Review O&M programs for all permittee owned facilities; update if necessary
- Implement all maintenance procedures for permittee owned facilities in accordance with O&M programs
- Implement program for MS4 infrastructure maintenance to reduce the discharge of pollutants

- Enclose all road salt storage piles or facilities and implemented winter road maintenance procedures to minimize the use of road salt
- Review as-built drawings for new and redevelopment to ensure compliance with post construction bylaws, regulations, or regulatory mechanism consistent with permit requirements

Provide any additional	l details on activities p	lanned for permit ye	ear 6 below:	

### Part V: Certification of Small MS4 Annual Report 2023

#### 40 CFR 144.32(d) Certification

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, I certify that the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:	Title:
Signature:  [Signatory may be a duly authorized representative]	Date: